



# Bangabandhu Water Treatment Plant

Khulna WASA, Pathorghata, Rupsha, Khulna-9240

## Daily Water Quality Report of Laboratory

Date of Testing: 19-04-2023

Test No: 1380

Weather: Sunny

Sl No	Test Item	Unit	Frequency	Detection limit (ECR-1997)	Instrument / Method	River Water	IPR Water	Raw water	Post-sedimentation / Pre-filters Water	Post-filters / Pre-Treated Water	Post-Treated Water
						Sampling Time: 09:10 AM	Sampling Time: 09:20 AM	Sampling Time: 10:02 AM	Sampling Time: 10:28 AM	Sampling Time: 10:40 AM	Sampling Time: 10:50 AM
1	Temperature	°C	day	20-30	Portable analyser-ST300			29.6	29.6	29.4	29.6
2	pH		day	6.5-8.5				8.34	8.22	8.07	7.98
3	Turbidity	NTU	day	<1 NTU	WTW PhotoFlex Turb	35.8	17.2	16.6	1.79	0.3	0.24
4	Color	pt-co	day	15	Portable analyser-AQ3700			103	25	12	3
5	Suspended Solid	mg/L	day	...				36	15	15	2
6	Taste and Odour		day	Odorless	Manual			Dirty Smell	Dirty Smell	No Objectionable	No Objectionable
7	Calcium	mg/L	Once a week	75	WTW PhotoFlex Turb						
8	ORP	mv	Once a week	...	WTW pH/ ION 3310						
9	Chloride	ppm	day	150-600	Mercuric Nitrate Titration			240	240		
Remark:											