



Bangabandhu Water Treatment Plant

Khulna WASA, Pathorghata, Rupsha, Khulna-9240

Daily Water Quality Record of Plant Apparatus

Date: 17-07-2023

Weather: Cloudy

Sl No	Test Item	Unit	Instrument Name	Purshall Flume	Pre Filter-1	Pre Filter-2	CWR
				Sampling Time: 10:12 AM	Sampling Time: 11:00 AM	Sampling Time: 11:02 AM	Sampling Time: 11:20 AM
1	pH		KROHNE pH Meter	8.47			7.84
2	Turbidity	NTU	KROHNE Turbidity Meter	87.72	8.4	0	0.14
3	Total Residual Chlorine	mg/L	KROHNE Chlorine Meter	0			0.24
Remark:							