



# Bangabandhu Water Treatment Plant

Khulna WASA, Pathorghata, Rupsha, Khulna-9240

## Daily Water Quality Report of Laboratory

Date of Testing: 26-07-2023

Test No: 1478

Weather: Sunny

Sl No	Test Item	Unit	Frequency	Detection limit (ECR-1997)	Instrument / Method	River Water	IPR Water	Raw water	Post-sedimentation / Pre-filters Water	Post-filters / Pre-Treated Water	Post-Treated Water
						Sampling Time: 09:24 AM	Sampling Time: 09:35 AM	Sampling Time: 10:30 AM	Sampling Time: 10:50 AM	Sampling Time: 11:00 AM	Sampling Time: 11:10 AM
1	Temperature	°C	day	20-30	Portable analyser-ST300			28.5	28.3	27.9	27.9
2	pH		day	6.5-8.5				8.49	8.31	8.26	8.08
3	Turbidity	NTU	day	<1 NTU	WTW PhotoFlex Turb	161	37.6	34.6	1.84	0.19	0.17
4	Color	pt-co	day	15	Portable analyser-AQ3700			228	24	12	12
5	Suspended Solid	mg/L	day	...				187	39	39	2
6	Taste and Odour		day	Odorless	Manual			Dirty Smell	Dirty Smell	No Objectionable	No Objectionable
7	Calcium	mg/L	Once a week	75	WTW PhotoFlex Turb						
8	ORP	mv	Once a week	...	WTW pH/ ION 3310						
9	Chloride	ppm	day	150-600	Mercuric Nitrate Titration			40	70		
Remark:											