



# Bangabandhu Water Treatment Plant

Khulna WASA, Pathorghata, Rupsha, Khulna-9240

## Daily Water Quality Record of Plant Apparatus

Date: 11-08-2023

Weather: Cloudy

Sl No	Test Item	Unit	Instrument Name	Purshall Flume	Pre Filter-1	Pre Filter-2	CWR
				Sampling Time: 10:31 AM	Sampling Time: 11:01 AM	Sampling Time: 11:02 AM	Sampling Time: 11:32 AM
1	pH		KROHNE pH Meter	8.5			7.83
2	Turbidity	NTU	KROHNE Turbidity Meter	49	1.5	0	0.18
3	Total Residual Chlorine	mg/L	KROHNE Chlorine Meter	0			0.22
<b>Remark:</b>							